


SEELEVEL II™

709-RVC NLP Wiring Diagram



⚠ WARNING: If the common alarm device exceeds the maximum rating of 1 amp a relay should be used.